## DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

# WELDING INSPECTION REPORT

Resident Engineer: Siegenthaler, Peter **Report No:** WIR-024354

Address: 333 Burma Road **Date Inspected:** 11-Jun-2011

City: Oakland, CA 94607

**OSM Arrival Time:** 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

**CWI Name:** Lu Hua Jie **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No **Weld Procedures Followed:** Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:** 

34-0006 **Bridge No: Component:** OBG

## **Summary of Items Observed:**

On this day CALTRANS OSM Quality Assurance(QA) Inspector Mr. Shrikant Utekar was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island in Shanghai, China. The QA Inspector observed and/or found the following:

TRIAL ASSEMBLY YARD

MAGNETIC PARTICLE TESTING

**OBG 14 EAST** 

ZPMC NWIT No: 09429

This QA Inspector performed Magnetic Particle Testing (MT) of approximately 15% of the length previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an (MT) report on this date. The members are identified as OBG 14East. The weld designations are as follows:

SEG3019Q-1-162, 288, 289; SEG3019R-164, 178, 179 SEG3019T-064 SEG3019S-270, 271, 260 SEG3019X-004, 005, 006, 007

BLAST SHOP #4

# WELDING INSPECTION REPORT

(Continued Page 2 of 2)

#### **ULTRASONIC TESTING**

### **OBG SEGMENT 13CW**

ABF Report No: UT-13W-055R1

This QA Inspector performed verification Ultrasonic Testing in accordance with ABF/CT Pattern "D" UT Procedure 001 Revision 1. All recordable Indications if found were recorded on a separate data sheet that Caltrans QA generates after performing a joint inspection with ABF ultrasonic testing personnel. The location of the inspection was identified as the weld between side panel and bottom panel of OBG segment 13CW on cross beam side. The weld designations were as follows:

SEG3015A-012

#### **OBG SEGMENT 13BW**

ABF Report No: UT-13W-056R1

This QA Inspector performed verification Ultrasonic Testing in accordance with ABF/CT Pattern "D" UT Procedure 001 Revision 1. All recordable Indications if found were recorded on a separate data sheet that Caltrans QA generates after performing a joint inspection with ABF ultrasonic testing personnel. The location of the inspection was identified as the weld between side panel and bottom panel of OBG segment 13BW on counter weight side. The weld designations were as follows:

#### SEG3014A-009

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

# **Summary of Conversations:**

No significant conversations were reported on this date.

#### **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, +(86) 1500 042 2372, who represents the Office of Structural Materials for your project.

Inspected By:	Utekar,Shrikant	Quality Assurance Inspector
Reviewed By:	Peterson,Art	QA Reviewer